


# Heat Treatment

## Heat Treatment (H. T.):

*A combination of heating & cooling operations, timed and applied to material or alloy in the solid state in a way that will produce a desired properties.*

*All basic (H. T.) of steel involves the transformation or decomposition of ( $\gamma$ ).*



## Types of (H. T.) of steel:

- a - Annealing Process.*
- b - Hardening by Continuous cooling.*
- c - Isothermal treatment.*

## The purpose of Annealing Process:

- 1 - Softening.*
- 2 - Improvement machinability.*
- 3 - Stress relief.*
- 4 - Grain refinement.*
- 5 - Homogenizing.*

## Steps of Annealing Process



- 1 - Heating above  $A_3$ .
- 2 - Hold at a temperature for a definite time.
- 3 - Cooling to the Room Temperature ( R. T. ) at slow rate.

## Types of Annealing Process:

- 1 - Full Annealing.
- 2 - Homogenizing.
- 3 - Normalizing.
- 4 - Stress relief anneal.
- 5 - Process Anneal ( Recrystallization – Anneal).
- 6 - Spherodizing.

## Full Annealing:


- ❖ Heating the Steel to the proper temp. and then cooling slowly through the transformation range ( in furnace ).
- ❖ The purpose of annealing  $\longrightarrow$  ( a ) - refine the grain. ( b ) - softness. ( c ) - improve electrical & magnetic properties. ( d ) - improve machinability.
- ❖ Refinement of the grain size of hypoeutectoid steel will occur about 50 °f above the lower critical temp. line (  $A_{3,1}$  ). See fig. 2.



**Fig. (2) The Change in microstructure during annealing of:**

**( a ) - 0.2% C.**

**( b ) - 1.0% C.**



## Homogenizing Treatment:

- ❖ A heat treatment of an alloy intended to make it uniform in composition by eliminating Coring & Concentration gradient.
- ❖ It is achieved by heating to a temp. (  $1100 - 1200\text{ }^{\circ}\text{C}$  ) for (  $10 - 20\text{ hour}$  ) followed by slow cooling in air or furnace.
- ❖ Sometimes needed to refine the coarse grains.

## Normalizing:

❖ It is carried out by heating to (  $100\text{ }^{\circ}\text{f}$  ) above (  $A_3$  ) or (  $A_{\text{cem}}$  ) followed by cooling in still air to Room Temp. (  $R_T$  ) to :

- produce harder & stronger steel than annealing.
- improve machinability.
- modify & refine cast dendritic structure.
- refine the grain & homogenize the structure.

❖ less proeutectoid (  $\alpha$  ) in normalized hypoeutectoid steel & less proeutectoid Cementite (  $\text{Fe}_3\text{C}$  ) in hypereutectoid steel as compared with annealed one because of there is less time for the formation of proeutectoid constituent.

❖ The faster the cooling rate, the lower the temp. of (  $\gamma$  ) transformation and the finer the Pearlite ( see fig. 3 ).





Fig. (3) The difference in P structure due to annealing & Normalizing

## Stress relief annealing:

- ❖ It is useful in removing residual stresses due to Cold Work ( C. W. ) process.
- ❖ It is carried out at a Temp. below (  $A_1$  ) ( 1000 – 1200 °f ).

## Process Annealing (Recrystallization – Anneal):

- ❖ It is used in the sheet & wire industries after ( C. W. ) see ( fig. 4 ).
- ❖ It is carried out by heating the steel to a Temp. below (  $A_1$  ) ( 1000 – 1250 °f ).



**Fig. (4) The cold – work cycle & Recrystallization diagram**



# Spherodizing:

❖ This process will produce a Spheroidal or Globular form of carbide in ( $\alpha$ ) matrix ( as shown in fig. 5 ) to improve machinability.

❖ One of the following methods may be used for Spherodizing:

1 - prolonged holding at a Temp. just below ( $A_1$ ).

2 - Heating & cooling alternatively between a Temp. that just above and just below ( $A_1$ ).

3 - Heating to a Temp. above ( $A_1$ ) and then either cooling very slowly in furnace or holding at a Temp. just below ( $A_1$ ).




Fig. ( 5 ): Stages of Spheroidized Annealing.