


MILLING

Q1: Draw a hand sketch showing the basic parts of the milling machine and refer to the headstock, spindle, tool, work-piece, table, cross slide and the base.



Q1: Draw a hand sketch showing the basic parts of the milling operation and refer to the tool, chip, work surface, depth, feed per tooth, work feed, machined surface and the direction of rotation.

